

Date: Wednesday, 06/09/2006 11:05:02 AM
 User: Linda Lacelle

Process Sheet

Customer : CU-DAR001 Dart Helicopters Services	Drawing Name : GPS RECEIVER HOUSING
Job Number : 28417	
Estimate Number : 12517	
P.O. Number : N/A	Part Number : D3514043
This Issue : 06/09/2006 S.O. No. : N/A	Drawing Number : UNDER REVIEW <i>E 06-09-05</i>
Prsht Rev. : NC	Project Number : N/A
First Issue : N/A Type : SMALL /MED FAB	Drawing Revision : N/A
Previous Run : N/A	Material : N/A
Written By : <i>E</i>	Due Date : 13/09/2006 Qty: 1 Um: Each
Checked & Approved By :	
Comment : Est Rev:A New Issue 06-08-30 EC	

Additional Product

PRELIMINARY ISSUE

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	D35143 - missing	BOX TOP (TOP MOUNTED)
-----	------------------	-----------------------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

BOX TOP (BOTTOM MOUNTED)

Batch: *B-28418**CB 07.03.08*

2.0	D35147	BOX BOTTOM (TOP MOUNTED)
-----	--------	--------------------------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

BOX BOTTOM (BOTTOM MOUNTED)

Batch: *B-28418**CB 07.03.08*

3.0	D35149	HOOD
-----	--------	------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

HOOD

Batch: *B-28358* - *B28420**CB 07.03.08*

4.0	D3524041 - missing	UPPER AND LOWER PLATE
-----	--------------------	-----------------------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

UPPER AND LOWER PLATE

Batch: *00053A**CB 07.03.08*

5.0	MS21072L06	ANCHOR NUT
-----	------------	------------



Comment: Qty.: 4.0000 Each(s)/Unit Total : 4.0000 Each(s)

ANCHOR NUT

Batch: *17101760**SB 07/03/08*

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 06/09/2006 11:05:02 AM
User: Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: GPS RECEIVER HOUSING

Job Number: 28417

Part Number: D3514043

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

MS20426AD33

RIVET



Comment: Qty.: 8.0000 Each(s)/Unit Total : 8.0000 Each(s)

RIVET

Batch: M19099

SB 07/03/08

7.0

MS20426AD45

Rivet



Comment: Qty.: 11.0000 Each(s)/Unit Total : 11.0000 Each(s)

Rivet

Batch: M1021

SB 07/03/08

8.0

MS20426AD48

RIVET



Comment: Qty.: 4.0000 Each(s)/Unit Total : 4.0000 Each(s)

RIVET

Batch: M12665

SB 06/09/21

9.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

Assemble as per dwg D3514

SB 06/09/21

①

①

□

10.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

11.0

POWDER COATING

POWDER COATING



Comment: POWDER COATING

Powder Coat Black Sandtex (Ref: 4.3.5.7) as per QSI 005 4.3

not required
CB

12.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

not required
CB

13.0

D35211

BALL



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

BALL

Batch: B28359

CB 07.03.08

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
07.03.08	14.0 15.0 16.0 18.8 20.0	parts will be taken From D3514-041 B/N 28416 For testing	CB	07.03.08				
07.03.08	11.0 12.0 17.0	not required For testing	CB	07.03.08				

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 06/09/2006 11:05:02 AM
User: Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: GPS RECEIVER HOUSING

Job Number: 28417

Part Number: D3514043

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

14.0	D35221 - missing	GASKET
------	------------------	--------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

GASKET

Batch: B28360

15.0	D35231 - missing	LEG
------	------------------	-----



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

LEG

Batch: 00053A

16.0	D35241 - missing	LOWER PLATE
------	------------------	-------------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

LOWER PLATE

Batch: 00053A

17.0	D35261 - missing	RUBBER SEAL
------	------------------	-------------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

RUBBER SEAL

Batch:

not required for testing CB

18.0	AN316A missing	Bolt
------	----------------	------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Bolt

Batch: 101884

19.0	AN936B10 missing	WASHER
------	------------------	--------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

WASHER

Batch: 101760

CB 07.03.08

20.0	AN960JD10	Washer
------	-----------	--------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Washer

Batch: 100774

CB 07.03.08

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes ☐ No ☒ DQA: ☒ Date: 07/07/24
 QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 06/09/2006 11:05:02 AM
User: Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: GPS RECEIVER HOUSING

Job Number: 28417

Part Number: D3514043

Job Number:



Seq. #:

Machine Or Operation:

Description :

21.0

MS24693S27

SCREW



Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s)

SCREW

Batch: 102147

CB 07.03.08

22.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

Assemble as per dwg D3514

23.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

24.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: _____

N/A
prototype

CB

25.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: Inspection Level 21

①
07/07/04

Job Completion



PART WENT TO HAI. PART NOT APPROVED AND NOT AIRWORTHY.

CB 07.07.13

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____


QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

PRELIMINARY ISSUE

DESIGN CB	DRAWN BY CB	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED	APPROVED	DRAWING NO. D3514	REV. A SHEET 2 OF 7
DATE 06.05.03	TITLE GPS RECEIVER HOUSING SCALE 1:4		



EST done
UNDER REVIEW

06.08.22 CB

prototype

PARTS LIST

QTY.	P/N	DESCRIPTION
X	D3514-043	TOP MOUNTED GPS RECEIVER HOUSING
1	D3514-3	BOX TOP (TOP MOUNTED) <i>missing</i>
1	D3514-7	BOX BOTTOM (TOP MOUNTED) <i>missing</i>
1	D3514-9	HOOD <i>wrong B/N</i>
1	D3521-1	BALL <i>missing</i>
1	D3522-1	GASKET <i>missing</i>
1	D3523-1	LEG <i>missing</i>
1	D3524-1	LOWER PLATE <i>missing</i>
1	D3524-041	UPPER PLATE ASSEMBLY <i>missing</i>
1	D3526-1	RUBBER SEAL <i>missing</i>
1	AN3-16A	BOLT <i>missing</i>
1	AN936-B10	WASHER <i>missing</i>
18	MS20426AD3-4	RIVET <i>AD3-3</i> M19099
11	MS20426AD4-5	RIVET <i>AD3-4</i> M1021
4	MS20426AD4-8	RIVET M12665
4	MS21072-06	ANCHOR NUT M101760
4	MS24693-S27	SCREWS <i>missing</i>

D3514-043 GPS RECEIVER HOUSING(TOP MOUNTED)

NOTE:

1) POWDER COAT ASSEMBLY OF D3514-3, D3514-7, D3514-9, D3524-3 AND MS21072-06 BLACK SANDTEX (4.3.5.7) PER DART QSI 005 4.3.

2) INSTALL D3521-1, D3522-1, D3523-1, D3524-1 AND D3526-1 AFTER PAINT

COPYRIGHT © 2006 BY DART AEROSPACE LTD.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.